



UNIVERSAL BRACKET INSTALLATION MANUAL


Model: UBL1110




1. Place component "A" on the back of the bracket and fasten it with two screws.




2. Run the installation wire through the component "B". Fasten the component "B" to the wall with two screws.



3. Make a hole in the detector's back cover to run through the installation wire. Run the wire through component "A" inside the detector. Attach the detector cover (component "A") to the component "B".



4. Connect the wires to terminal blocks of PCB and close the detector's cover. Adjust the desirable angle and fix it with two screws.



5. Use additional prop to mount the detector with an angle to the wall 15°, on for corner mounting.

- Bracket for detector (angle=30°)
- Additional prop (angle=15°)
- Horizontal - vertical adjustment of the bracket with additional prop (angle=45°)

G.S.N. ELECTRONIC COMPANY LTD.